

V2.2.0 (2017-09-15)

---

- 1: Add 2016 New passat ABS code generate.
- 2: Add 2016 santana steering config data.VAG Number:1S1909144P.
- 3: Add Magotan B8L rearlid config data.VAG Number:5Q0959107J.
- 4: Fix other bugs.

V2.1.9 (2017-08-15)

---

- 1: Add Sharan PLA3.0\_7N0919475F parameter file.
- 2: Add 4S repair shop menu.
- 3: Add Scan&save car modules information.
- 4: Add 02E six speeds DSG basic setting.
- 5: Add SD card reader.(system setting->).
- 6: Add Auto lock door(speed>15km/h).
- 7: Add Auto unlock door(remove key).
- 8: Fix Other bugs.

V2.1.8 (2017-07-18)

---

- 1: Add EA111 UDS engine check oil level.
- 2: Add EA111 UDS genine clear value adapt throttle.
- 3: Add UDS EPB set "VIN check" option.
- 4: Add GTI7.5 3Q0907338 parameter file.
- 5: Add Audi start-stop setting.
- 6: Add Audi A4(2017) sports needle.
- 7: Fix 4B unit connection bug.

8:Change some description of parameter files.

---

V2.1.7 (2017-06-20)

1:Add PQ35 enable PLA3.0.

2:Add golf6 1.4T 7DSG ABS code generate.

3:Add many configuration parameter files.

4:Fix other bug.

---

V2.1.6 (2017-05-15)

1:Add magotan/CC replace new comfort module.

2:Add MIB RCTA sensors setting.

3:Add some controller configuration parameter files.

4:Add SD card format &create folders.

5:Add recover coding after refresh parameter files.

6:Fix other bug.

---

V2.1.5 (2017-05-08)

1:Fix some firmware file parse failed.

2:Add many configuration parameter files.

---

V2.1.4 (2017-04-27)

1:parameter refresh write multi data blocks one time.

2:Fix can't auto detect instrument type when read PIN.

3:Add parameter files as below:

3.1: New lavida steering assistance 180909144.

3.2: skoda PQ superb kessy.

3.3: lamando kessy three antennas.

3.4: VW411 kessy 5K0959434H.

3.5: VW411 BCM light data. 5K0937087AG.

3.6: VW411 DCC 3C0907376x.

3.7: VW411 gateway(active/deactive MKE).

3.8: VW411 DSP config data(fender/dynaudio).

3.9: VW411CS headlight AFS.5M0907357G.

3.10:VW411CS front camera,3Q0980654.

V2.1.3 (2017-04-22)

---

1:Add 2017 sharan light data.

2:Add xenon static AFS.

3:Fix reprogram BCM firmware bug.

4:Fix reprogram UDS module bug.

5:Add parameter files as below:

5.1:lamando ACC 5Q0907572A/B/D.

5.2: lamando PDC 5Q0919294.

5.3: lamando PLA 5Q0919298A/D.

5.4: lamando Kessy 5Q0959435A.

5.5: lamando Gateway 5Q0907530N/Q.

5.6: lamando rear left door 5Q4959393B/595B.

5.7: lamando rear right door 5Q4959393B/595B.

5.8: VW37x headlight AFS 5Q0907357/A/D.

5.9 ŁS VW37x SWA 5Q0907686.

5.10: VW37x front camera 5Q0980653C/E/F.

5.11: VW37x steering assistance 5Q0909144P.

V2.1.2 (2017-04-13)

---

1:Add PQ MIB clear DTC after updating firmware.

2:Add PQ MIB golden menu.

3:Add sharan sliding door basic setting.

4:Add Lane keep for 30 seconds.

5:Add OAM DSG Software Nr Index Version GKBS.

6:Add some parameter files.

7:Fix some bugs.

V2.1.1 (2017-04-01)

---

1:Fix SD card refresh xml parameter files bug.

2:Add PQ MIB adapt dashboard test.

3:Add NEC+24C64 EEPROM function.

3.1:Park braking type.

3.2:Number of fuel tanks.

3.3:MFW type.

3.4:Temperature unit.

3.5:Distance unit.

3.6:Speed unit.

3.7:Time format.

3.8:Comsumption format.

- 3.9:Sun roof indicator.
- 3.10:Side indicator.
- 3.11:DPF indicator.
- 3.12:Parking indicator.
- 3.13:Engine indicator.
- 3.14:Oil temperature menu.
- 3.15:Refuel volume menu.
- 3.16:Support menu.
- 3.17:Logos.
- 3.18:Alternative logos.

V2.1.0 (2017-03-27)

---

- 1:Add gateway list state.
- 2:Add touranL auto air conditioner wind speed display.
- 3:Add VAG addtional information code description library.
- 4:Add PQ MIB amplifier setting.
- 5:Add 2017 3D color dashboard golden menu setting.
- 6:Add lamando1.4T driver door/passenger door config parameter files
- 7:Add NMS soundsystem config parameter files.

V2.0.9 (2017-03-17)

---

- 1:Add TiguanL parameter files.
- 2:Fix Magotan/CC convience adaption.
- 3:Fix controller adaption menu.
- 4:ODX firmware support up to 60M.

5:Fix color dashboard reprogramming error.

5:Fix others.

V2.0.8 (2017-03-02)

---

1:Add temporary parking lock door.

2:Add air conditioner self check mode.

V2.0.7 (2017-02-24) ©

---

1:Add replace PQ35 dashboard(UDS).

2:Add LED license plate alarm.

3:Fix other error.

V2.0.6 (2017-02-22)

---

1:Add NEC+24C64 EEPROM function.

1.1:enable dashboard needle self check.

1.2:enable backlight of scales.

1.3:enable backlight of needles.

1.4:enable backlight of needles for 30 seconds after locking.

1.5:dashboard production mode.

1.6:driving mode.

1.7:handbrake light position.

1.8:welcome menu.

1.9:close engine oil sensor prompt.

1.10:digital speed.

1.11:oil tank feature.

1.12:solve needle shaking after reprogramming firmware.

1.13:oil tank opening prompt.

1.14:DRL indicator.

1.15:white screen LCD type.

1.16:enable TwinDrive.

1.17:trailer indicator.

1.18:dipped headlight indicator.

1.19:front fog light indicator.

1.20:shift gear position P/N prompt.

1.21:speed scales 240/260/280/300km/h.

2:Add uds dashboard service interval setting.

3:Add change new dashboard milleage.

4:Add close dashboard production mode.

5:Add support chinese of SD card files.

6:Add BCM read/write remote keys ID.

7:Fix xml parameter files parse error.

8:Add static DTCs prompt.

V2.0.5 (2017-01-11)

---

1:Add reprogramming uds unit,support frf/odx format.

2:Add some parameter files.

3:Add DSG gearbox go into neutral gear.

4:Fix other errors.

V2.0.4 (2016-12-14)

---

1:Add description of many parameter files.

2:Add some parameter files.

3:Fix kwp2000 adaption error.

4:Fix kwp1281 communication error.

5:Fix uds protocal communication error.

6:Fix other errors.

V2.0.3 (2016-12-01)

---

1:Add sgo format firmware reprogramming.

2:Touareg set four brake light.

3:PQ MIB dynaudio mode.

4:PQ MIB engineering mode.

5:PQ MIB connect two phones.

6:TRW460 ABS coding.

V2.0.2 (2016-11-21)

---

1:Add reprogramming steering assistance curve.

2:Add some config parameter files.

3:Fix uds dashboard can't change milleage.

V2.0.1 (2016-06-23)

---

\* Init version

---

this is test!